

DELHI PARKS & GARDENS SOCIETY

(A Society Registered under the Societies Registration Act of XXI, 1860)
(Registration No. S/62922/2008)

DEPARTMENT OF ENVIRONMENT

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

“C” Wing, 6Th Level, Delhi Secretariat Building, I P Estate, New Delhi - 110002

Tele-Fax: 011-23392736 E-mail ceodpgsenv.delhi@nic.in

No.F.1(01)/DPGS/2012-13/ 6151

Dated:- 9/10/14

MINUTES OF MEETING

A meeting was held in the office of CEO, DPGS/Nodal Officer-Water Bodies on 17.9.2014 at 3:00 pm to review the status of water bodies and action plan regarding their revival and development pertaining to North Distt. All officers/officials from various agencies were called and they attended the meeting. The following attended the meeting:-

1. Sh. C.D. Mishra, ASI (M) 9968629277
2. Dr. Ashish Priyadarsh, NDMC (M) 9717787547
3. Sh. Anil Kumar, AO/Civil/Lab, NDMC (M) 9717788132
4. Sh. Prem Chandra, Dy. Director (Hort.) DDA, Division V, (Rohini) (M) 9910325999
5. Sh. Vishnu Dutt Sharma, AD, HD, V, DDA (M) 9868837922
6. Sh. S.B. Yadav, Dy. Director (Hort.), DDA, Division – X (M) 9868405152
7. Sh. Mahender Pal Singh, BDO (North) (M) 9213032720
8. Sh. Sunil Kumar Sharma, AE, DJB, O/o EE (C) DR III (M) 9650094425
9. Sh. Vivek, JE, DJB, O/o EE(O) DR III (M) 9650844141
10. Sh. Rajpal Singh Tomar, HA (Env. Deptt.) (M) 8527791531
11. Sh. Rajbir Singh, HA (HQ) (M) 8527791525

Distt. – North:-

1. Akbarpur majra (a) 62 (6-10): -

It belongs to BDO. BDO staff informed that demarcation has been done by 3 sides. Direction has been given to plant more and more trees.

2. Akbarpur majra (b) 29/1/2 (1-17): -

It belongs to BDO. Community Centre exists. Direction has been given to install Rain Water Harvesting system and tree plantation in vacant land.

3. Akbarpur majra (c) 63min (00-19):-

It belongs to BDO. Gram Sabha Land. BDO staff informed that they have already written a letter for Khatima (earmark) to Revenue Deptt. Direction has been given that to cover the area through boundary wall and plantation.

4. Alipur 64/27(19-00):-

It belongs to BDO. Water body developed. Direction has been given for tree plantation.

5. Auchandi (a) 45//6/1 (205), 7min (3-0) total area(5-5):-

It belongs to BDO. Well developed but sewage is flowing into it. Direction has been given to Delhi Jal Board to remove the sewage flowing in to the water body and submit the report. Plantation around the water body.

6. Auchandi (b)85 (10-3)

It belongs to BDO. Well developed but sewage is flowing into it. Direction has been given to Delhi Jal Board to remove the sewage flowing in to the water body and submit the report. Plantation around the water body.

7. Auchandi (c)88 (7-0)

It belongs to BDO. Direction has been given to inspect the water body. TSM required. Direction has been given Delhi Jal Board to remove the sewage flowing in to the water body and submit the report. Plantation around the water body.

8. Auchandi (d) 89 (25-10)

It belongs to BDO. Direction has been given to inspect the water body and protect the entire area.

9. Bakhtawar pur (a) 115 (19-4)

It belongs to BDO. Water body is exist on Tajpur Road. Kabristan exists on the water body land. Direction has been given for tree plantation.

10. Bakhtawar pur (b)110 (22-4):-

It belongs to BDO. Water body exists on Harmidpur Road. Kabli Kikkar already there.

11. Bakhtawar pur (c)113 (9-10):-

It belongs to BDO. Water body exists on Bakhtawarpur to Hamidpur Road. Direction has been given for TSM survey tree plantation.

12. Bakhtawar pur (d)109 min (10-16):-

It belongs to BDO. BDO staff informed that date has been fixed for demolition for partly encroachment. Direction has been given Delhi Jal Board to remove the sewage coming into the water body. Plantation to be done.

13. Bakhtawar pur (e)111 (04-18):-

It belongs to BDO. Encroachment exists on the water body. Direction has been given to get the demarcation done at the earliest.

14. Bankner (a) 37/28 &29 (14-8):-

It belongs to BDO. Court Case pending in the court of Deputy Commissioner.

15. Bankner (b)43/26 (14-08):-

It belongs to BDO. Water body in good condition. Already developed.

16. Bankner (c)42/27min (18-10):-

It belongs to BDO. Partly encroached by way of temple and park. Direction has been given to maintain as green area by planting more and more trees.

17. Bankner (d) 38//28/2 (23-18)

It belongs to BDO. BDO staff informed that incomplete stadium structure is lying there. Direction has been given for inspection to be done by BDO staff alongwith concerned HA and comments to be submitted.

18. Bankner (e)10//26 (0-4)W:-

It belongs to BDO. Encroachment in the form of agriculture. Direction has been given that the demarcation to be done.

19. Bankner (f)32//28(0-5):-

It belongs to BDO. Direction has been given to BDO staff to get the area inspected and submit the report.

20. Bankner (g)32//29 (0-6):-

It belongs to BDO. Direction has been given to BDO staff to get the area inspected and submit the report.

21. Bankner (h)37//26,27 (0-6):-

It belongs to BDO. It is near to the water body at G. No. 116 and both the Kh. Nos. should be developed together. Direction has been given the BDO staff to inspect the water body.

22. Bajitpur thakran (a)22//4(04-16) 5(04-16) Total-(09-12):-

It belongs to BDO. Well developed water body. Direction has been given to BDO to inspect the water body alongwith concerned HA and submit the report.

23. Bajitpur thakran (b)30//9/1 (02-06) 10(3-08) Total-(05-14)

It belongs to BDO. Boundary wall completed. Plantation needs to be done.

24. Bajitpur thakran (c) 8//17 (03-18) 18 (4-16) Total- 08-14):-

It belongs to BDO. Sewage is flowing into the water body. Delhi Jal Board to stop the sewage flow. Encroachment to be removed. According to GSDL there is another water body found near the water body having khasra no. 8/23/0. Direction has been given for plantation.

25. Bajitpur thakran (d)76//8 (04-14):-

It belongs to BDO. Boundary wall has been completed. Direction has been given for tree plantation.

26. Bawana (a)202/2 (11-10):-

It belongs to BDO. Court case pending in High Court. Demolition has been completed. To be discussed with Court Commissioner. Direction has been given to BDO staff to get the area inspected alongwith concerned HA and submit the report.

27. Bawana (b)74/18 (04-16) 23(04-14) Total area - 9-10:-

It belongs to BDO. Well developed water body.

28. Bawana (c)108/25 (04-16):-

Seasonal wet. Direction has been given for inspection by BDO staff alongwith concerned HA. Adjoining there is another water body.

29. Bawana (d) 203 (07-03):-

It belongs to BDO. Rain water harvesting system to be installed. Direction has been given for inspection by BDO staff alongwith concerned HA and plantation around the water body.

30. Bawana (e)130//4min (03-16):-

It belongs to BDO. Well developed water body.

31. Bawana (f)161//1 (01-12):-

It belongs to BDO. Well developed water body.

32. Bawana (g) 205 (02-11):-

It belongs to BDO. Dada Bhaiya Choupal and park. Direction has been given for inspection by BDO staff alongwith concerned HA and submit the report.

33. Bawana (h) 206 (06-13):-

It belongs to BDO. Partly encroached. Direction has been given to remove the encroachment.

34. Bawana (i)206/1min (09-17):-

It belongs to BDO. G. No. 135 and 136 are adjoining. Boundary wall to be made. Entire area to be protected.

35. Budhpur bizapur Old 21//15,16 new 33 (8-2):-

It belongs to BDO. Total pucca.

36. Bara Hindurao Khasra No. 319 (Area-1250 sq.mtrs.):

It belongs to ASI. Water body belongs to ASI. Forest department needs to be consulted for plantation.

37. Daryapur kalan (a) 107(19-17):-

It belongs to BDO. Well developed water body.

38. Daryapur kalan (b)71/29 (36-09):-

It belongs to BDO. As per the report of BDO demarcation is under progress.

39. Daryapur kalan (c)44/26 (03-12):-

It belongs to BDO. As per the report of BDO demarcation is under progress.

40. Daryapur kalan (d) 65/1&2 (9-12):-

It belongs to BDO. Land allotted under 20 point programme. Direction has been given for rain harvesting system and tree plantation. Adjoining there are two water bodies.

41. Daryapur kalan (e) 69/31(2-3):-

It belongs to BDO. Ambedkar park developed. Direction has been given for tree plantation.

42. Ghari khusro (a)222-223/1 (22-00):-

It belongs to BDO. There is no water body as per the statement of BDO staff. Direction has been given for inspection by BDO staff alongwith concerned HA.

43. Ghogha (a)193 (17-11):-

It belongs to BDO. Nearly 15 bigha land has been encroached. TSM survey is required.

44. Ghogha (b)180 (05-11):-

It belongs to BDO. Community centre exists. Rain water harvesting system to be installed.

45. Hamid pur (a) 47/1(9-16):-

It belongs to BDO. Sewage is flowing into the water body. Direction has been given to stop the sewage water and entire area to be inspected.

46. Hamid pur (b)31/41(10-18):-

It belongs to BDO. 20 point programme. Rest of the area should be maintained as green. Rain water harvesting system to be installed.

47. Hamid pur (c) 53 (0-15):-

It belongs to BDO. Park exists. Needs demarcation.

48. Hamid pur (d) 54(0-5):-

It belongs to BDO. Park exists. Needs demarcation.

49. Harewali (a)10/11(4-16),11/20min (2-11)10/21min(2-10) Total area (9-17):-

It belongs to BDO. Demarcation to be done. Direction has been given for tree plantation.

50. Harewali (b)11/16min(2-12):-

It belongs to BDO. Demarcation to be done. Direction has been given for tree plantation.

51. Harewali (c)11/25min(1-0):-

It belongs to BDO. Demarcation to be done. Direction has been given for tree plantation.

52. Harewali (d)19/19min(4-16) Total area (9-12):-

It belongs to BDO. Sewage is flowing into the water body. It has become dumping yard. Boundary wall to be made. Direction has been given for inspection by BDO staff alongwith concerned HA.

53. Hiranki (a)534, 535 (12-13):-

It belongs to BDO. Sewage is flowing into the water body. Delhi Jal Board has been directed to remove the sewage. Boundary wall to be repaired. Concerned HA to inspect the site for plantation.

54. Hiranki (b) 56/2(10-07):-

It belongs to BDO. Total pucca. Catchment area to be developed.

55. Holambi Kalan (a) 96/70(04-04)76(11-06) Total - 15-10):-

It belongs to BDO. Case pending in High Court. Demolition and TSM has been completed.

56. Holambi Kalan (b) 35/3 (03-08) 4(03-05) 4(03-05) 8(03-08) Total=(14-16):-

It belongs to BDO. Shamshan ghat and park exists. Direction has been given to BDO staff for TSM survey.

57. Holambi khurd (a)119 (43-8):-

It belongs to BDO. Direction has been given to BDO staff for TSM survey.

58. Holambi khurd (b)117, 118 (19-2):-

It belongs to BDO. Sewage is flowing into the water body. Delhi Jal Board has been directed to remove the sewage. Plantation to be done.

59. Ibrahimpur (a) 113/2(3-10):-

It belongs to BDO. Well developed water body. Boundary wall exists. Direction has been given to concerned HA to inspect the site for tree plantation.

60. Ibrahimpur (b)90 (4-09):-

It belongs to BDO. This water body is situated next to MCD primary School. Sewage is flowing into the water body. MCD has been directed to remove the sewage.

61. Jindpur (a) 8/04 min (1-16):-

It belongs to Forest. This water body is belongs to Forest Department. Direction has been given for tree plantation.

62. Jindpur (b) 49(1-15):-

It belongs to BDO. MCD park already developed. Direction has been given for inspection by concerned HA.

63. Jwala heri F/89:-

It belongs to DDA. Situated at A- Block, Pachim Vihar. Inspection to be done by DDA alongwith concerned HA.

64. Katewara (a) 473 (4-13)474(4-16) 477(4-16), 479(4-16) Total area (19-4):-

It belongs to BDO. Well developed and Temple exists. Direction has been given for inspection by concerned HA for plantation.

65. Katewara (b)692 (4-16):-

It belongs to BDO. Developed. Direction has been given for inspection by concerned HA for plantation.

66. Katewara (c)824 (7-01):-

It belongs to BDO. Temple exists. Plantation to be done on the vacant land.

67. Katewara 49(4-05) 50(5-09) total=(19-14):-

It belongs to BDO. Under 20 point programme. Rain water harvesting system and tree plantation.

68. Khera kalan (a)133(27-3)old No/52/26(22-16),37//26(4-6) Total area (27-2):-

It belongs to BDO. Well developed.

69. Khera kalan (b) 39//26 (18-16):-

It belongs to BDO. Community Centre and temple exists. Plantation has been done.

70. Khera kalan c) 134(6-10)old No/9/1(4-14),5/21(1-10),22/1(0-6) Total area) 6-10):-

It belongs to BDO. Direction has been given for inspection by concerned HA alongwith BDO staff.

71. Khera kalan (d) 52/26(22-16):-

It belongs to BDO. Already entered in G. No. 170.

72. Khera kalan (e) 143(0-2):-

It belongs to BDO.

73. Khera kalan (f) 168(0-6):-

It belongs to BDO.

74. Khera kalan (g) 206(0-2):-

It belongs to BDO.

75. Khera kalan (h) 220(0-6):-

It belongs to BDO.

76. Khera kalan (i) 74/26(0-1):-

It belongs to BDO.

77. Khera kalan (j) 125/26(0-1):-

It belongs to BDO.

78. Khera khurd (a) 237(28-16):-

It belongs to BDO. Boundary wall has been completed. Catchment area to be developed.

79. Khera khurd (b)268 (8-13):-

It belongs to BDO. Complete boundary wall. Dry. Direction has been given for inspection by concerned HA.

80. Khera khurd (c)269(7-14):-

It belongs to DDA. Land awarded to DDA vide award order no. 5/05-06. Direction has been given to DDA for plantation around the water body.

81. Khera khurd (d)277(0-10):-

It belongs to BDO. Delhi Jal Board Tank exists on the water body land.

82. Lam Pur (a)21//26(1-3):-

It belongs to BDO. Demarcation has been done.

83. Lam Pur (b)25//2 (5-6):-

It belongs to BDO. It belongs to BDO. It is wet natural pond. There is no boundary wall.

84. Lam Pur (c)50//4min (3-8):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

85. Lam Pur (d)50//6 (4-16):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

86. Lam Pur (e) 50//7 (4-16):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

87. Lam Pur (f) 50//15min (1-6):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

88. Lam Pur (g) 51//1 (0-7):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

89. Lam Pur (h) 54//11/2 (2-1):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

90. Lam Pur (i)37//19/1min (0-3):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

91. Lam Pur (j)37/19//2 (0-5):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

92. Lam Pur (k)37/19//21min(0-8):-

It belongs to BDO. As informed by BDO staff demarcation has been done and handed over to I&FC for boundary wall.

93. Lam Pur (l) 85/2(6-11):-

It belongs to BDO. Incomplete MPCC. Direction has been given for inspection and plantation.

94. Libas pur (a)24//3(2-7):-

It belongs to BDO. Under 20 point programme. Choupal and temples exists. Direction has been given for inspection by concerned HA alongwith BDO staff and clear the current position of the site.

95. Libas pur (b)27 (16-19):-

It belongs to BDO. Under 20 point programme. Direction has been given for inspection by concerned HA alongwith BDO staff.

96. Mohd pur ramjanpur 371/4:-

It belongs to BDO. Direction has been given to BDO staff to ask the revenue department for records.

97. Mungesh pur (a) 49(12-17):-

It belongs to BDO. It is dry and has wild plantation without boundary wall. Garbage is dumped at the site. Direction has been given to BDO to remove the garbage. Catchment area to be developed.

98. Mungesh pur (b)4//2 (4-16):-

It belongs to BDO. It is dry and its boundary wall is completed by 3 sides. Direction has been given to complete the work.

99. Mungesh pur (c)11//26 (4-16) :-

It belongs to BDO. Dry water body. Inspection to be done by the concerned HA alongwith BDO staff.

100. Mungesh pur (d) 314/2 (6-1),308/2 (0-15) total area (6-16):-

It belongs to BDO. Sewage is flowing into the water body. Delhi Jal Board has been directed to remove the sewage and submit the report. Inspection to be done by the concerned HA.

101. Nangal Thakran (a) 92 (19-9),92min (2-0) Asami Sher Singh s/o Nobat (2-4) Asami Bagwan s/o Mul chand Total area (23-9) as per khathoni:-

It belongs to BDO. Direction has been given for inspection by concerned HA alongwith BDO staff.

102. Nangal Thakran (b) 87 (9-7):-

It belongs to BDO. Well developed water body.

103. Nangal Thakran (c)9/3 (2-16) 4(04-16) 7(04-16) 8(04-16) total= (17-04):-

It belongs to BDO. Boundary has been completed. Direction has been given for inspection and plantation by concerned HA.

104. Nangal Thakran (d) 81 (14-12) 83(9-15) total=(24-07):-

It belongs to BDO. Needs boundary wall. Inspection to be done by concerned HA alongwith BDO staff.

105. Nangal Thakran (e) 90 (4-17):-

It belongs to BDO. This water body is adjacent to drain. Direction has been given for TSM survey and plantation.

106. Nai Sarak:-

It belongs to DDA. Market has been developed on the water body land.

107. Nangli puna 48min (3-11½):-

It belongs to BDO. Some area is under 20 point programme. TSM survey is required. Boundary wall to be completed. Entire area to be protected.

108. Narela (a) 61/26 (07-18):-

It belongs to MCD. Direction has been given to MCD to verify the ownership of the land by ADC. Plantation to be done on vacant land by the MCD Deptt.

109. Narela (b) 239 min (29-6):-

It belongs to BDO. Bus Terminal exists on some part of the land. Direction has been given for TSM survey and tree plantation. Joint inspection to be done by concerned HA alongwith BDO staff and submit the report on urgent basis.

110. Narela 396 (06-11):-

It belongs to MCD. The ownership of this water body has been transferred to MCD Department. Plantation to be done.

111. Naya bans (a) 42/28 (01-17):-

It belongs to BDO. It is a dry water body.

112. Naya bans (b)44/28 (05-17):-

It belongs to BDO. Boundary wall completed. Adjoining MCD School. Direction has been given for plantation.

113. Naya bans (c)12/29, 30 total area (07-05):-

It belongs to BDO. Situated on side of bhola ram marg. BDO staff informed in the meeting that this water body does not exists in their record. Direction has been given to BDO staff to inspect the water body area alongwith concerned HA and submit the report.

114. Naya bans (d)55/6,7,14,15 total area= (16-7)

It belongs to BDO. Direction has been given for TSM survey and inspection to be done alongwith concerned HA and BDO staff. Tree plantation to be done.

115. Naya bans (e)19/27 (7-5):-

It belongs to BDO. It is a dry water body. Boundary wall completed.

116. Palla:-

It belongs to BDO. BDO staff informed in the meeting that there is no water body exists as per their record. To be checked by the Court Commissioner.

117. Patti jahanuma:-

It belongs to BDO. BDO staff informed in the meeting that there is no water body exists as per their record. To be checked by the Court Commissioner.

118. Pehladpur bangar (a) 46/26 (10-18):-

It belongs to BDO. Sewage is flowing into the water body. Delhi Jal Board has been directed to stop the sullage flowing into the water body. Catchment area to be developed.

119. Pehladpur bangar (b)86/58 (9-7):-

It belongs to BDO. BDO informed that they have written to revenue department for demarcation. Sewage is flowing into the water body. Delhi Jal Board has been directed to stop the sullage flowing into the water body.

120. Pehladpur bangar (c)38/26(9-16):-

It belongs to BDO. As per the record of BDO this has been allotted to SC, ST financial corporation.

121. Pooth khurd 135(7-19):-

It belongs to BDO. Encroachment in the form of temple on some portion of this water body. BDO has been directed to protect the water body.

122. Pooth khurd (b)136/2 old 157 new (27-2):-

It belongs to BDO. BDO informed that there is 3 side boundary wall completed and due to encroachment one side boundary wall has not been made. Direction has been given to remove the encroachment and complete the boundary wall. Adjoining there is a water body near MCD park.

123. Rampura F/66 50/18,19:-

It belongs to DDA. This water body area is near to Railway Line. Direction has been given to DDA for tree plantation.

124. Harsh Vihar (village Saleempur majra madipur F/74) (a) 9996 sq. mtrs. 2.47 acres K No.206:-

It belongs to DDA. Park developed. Adjoining Kohat Enclave. Direction has been given for inspection and tree plantation.

125. Purana Quila – Baoli Khasra No. 499 (Area–675 sq.mtrs.):-

It belongs to ASI and well maintained.

126. Pitampura-A & Distt. Park Pitampura 862 to 871:-

It belongs to DDA. Area is 10 acre. Five water bodies exists. It has to be jointly inspected by DDA alongwith concerned HA.

127. Prasad Nagar (a) K No. 578(2800 sq. mtrs.):-

It belongs to DDA. Well developed water body. Inspection to be done.

128. Sanooth (a) 99(36-4):-

It belongs to BDO. Well developed water body.

129. Shabad daulat pur (a) 68(6-12):-

It belongs to BDO. Community centre exists. Direction has been given for rain water harvesting and plantation.

130. Shabad daulat pur (b)121/(13-7):-

It belongs to BDO. Govt. School exists. Rain water harvesting system to be installed by PWD. Plantation to be done.

131. Shabad daulat pur (c)128(5-9):-

It belongs to DDA. Joint inspection to be done.

132. Singhola (a)28//26(9-2):-

It belongs to BDO. Dry and well developed. Inspection to be done.

133. Singhola (b)12//26 (6-16):-

It belongs to BDO. It belongs to BDO. Developed. Sewage work is under progress. Sewage to be remove within one year.

134. Singhola (c)7//26/1(0-4):-

It belongs to BDO. This water body is adjacent to drain. Inspection to be done.

135. Singhu (a) 43 (9-19):-

It belongs to BDO. Boundary wall has been completed. Needs plantation.

136. Singhu (b)6/26 (9-1):-

It belongs to BDO. Boundary wall has been completed. Needs plantation.

137. Singhu (c)26/28 (3-12):-

It belongs to BDO. Boundary wall has been completed. Needs plantation.

138. Siraspur (a)162 (14-10):-

It belongs to DDA. EWS housing. Two water bodies adjoining. Inspection to be done by DDA.

139. Siraspur (b)625/3min (11-9):-

It belongs to BDO. Under developed. As per the BDO staff three side boundary wall is needed. The site has been converted into dumping yard.

140. Siraspur (c)759 (10-3):-

It belongs to BDO. It has developed and dry.

141. Siraspur (d) 968/2 (0-5):-

It belongs to BDO. Inspection by Court Commissioner.

142. Sultanpur dabas (a)35//37 (7-16):-

It belongs to BDO. Well developed.

143. Sultanpur dabas (b)72//26/2 (5-2):-

It belongs to BDO. Adjoining there is another water body.

144. Sultanpur dabas (c) 96//1/1 (30-11):-

It belongs to BDO. One side boundary wall is needed. Direction has been given to BDO to complete the work on urgent basis.

145. Sungar pur (a)13/26(4-16) 24/27(1-8) total area (6-4):-

It belongs to BDO. River side. Inspection to be done by BDO alongwith concerned HA.

146. Tajpur kalan (a) 42(6-16):-

It belongs to BDO. It has developed.

147. Tajpur kalan (b) 41min (6-13):-

It belongs to BDO. It has developed.

148. Tajpur kalan (c)39min (7-17.5):-

It belongs to BDO. Demarcation to be done after demolition of encroachment.

149. Tehri daulat pur (80-0):-

It belongs to BDO. It has developed and good for plantation.

150. Tigi pur (a)11//13(1-4):-

It belongs to BDO. It has developed. Temple exists on the land of water body.

151. Tigi pur (b)11/12 (1-13) 58(3-18) total area (5-11):-

It belongs to BDO. Well Developed. Inspection to be done by concerned HA for plantation.

152. Tigi pur (c)14/14min (0-14) 15(4-16) total area (5-10):-

It belongs to MCD. Direction has been given for tree plantation.

153. Tikri khurd (a)15//9 (4-16):-

It belongs to DDA. DDA to develop the water body. Direction has been given for tree plantation.

154. Tikri khurd (b)30//1 (4-16),30//3 (4-15), 30//4 (0-9) Total area (10-0):-


It belongs to DDA. DDA to develop the water body. Direction has been given for tree plantation.

155. Qadi pur:-

It belongs to BDO. As per the information given by BDO there is no water body exists in the revenue record.

156. Qulakpur:-

It belongs to BDO. As per the information given by BDO there is no water body exists in the revenue record.




(Dr. S.D. Singh)
CEO-DPGS,

Nodal officer, Water Bodies

To,

1. **Deputy Commissioner (North)**, 1, Kripa Narain Marg, Delhi - 110054
2. **BDO (North)**, Shaheed Smarak, Near MPCT, Alipur, Delhi - 110036
3. **Engineer in Chief**, North MCD, 6th Floor, Civic Centre, Minto Road, New Delhi - 02
4. **Chief Engineer (Dr) P- I**, Delhi Jal Board, Varunalaya, Phase-II, Jhandewalan, Karol Bagh, New Delhi - 110005
5. **Superintending Engineer/Nodal Officer-Water Bodies**, DDA, Dwarka, Near Manglapuri, New Delhi - 110030
6. **SE (HQ) North Zone**, DDA, 18th Floor, Vikas Minar, New Delhi - 110002
7. **SE (HQ) (Rohini)**, DDA, Madhubhan Chowk, DDA Office Complex, Rohini, Delhi - 110085
8. **Deputy Director (Hort.)**, Division No. X, LSC, Opp. GTK. Depot, Jahangir Puri, Delhi
9. **Superintending Archaeologist, Delhi Circle**, Safdarjung's Tomb, New Delhi 110003



(Dr. S.D. Singh)
CEO-DPGS,

Nodal officer, Water Bodies