VIVEK KUMAR TANDON ADVOCATE

**Chambers:** 

404, Lawyers' Chambers, Delhi High Court Complex, Sher Shah Road, New Delhi-110003. 529, Lawyers' Chambers, Western Wing (Criminal Side), Tis Hazari Courts, Delhi-110054.

Phones: 2338-4570 2393-5290

Residence-Cum-Office:

31/26, East Patel Nagar, New Delhi-110008. Mobile – 98101-77733 **Tele-faxes:** 2585-0970 2585-4970 2578-9608

E-mail: <a href="mailto:tandonadvocates@gmail.com">tandonadvocates@gmail.com</a>
vivekkumartandon@gmail.com

MINUTES OF MEETING OF SITE (DISTRICT NORTH-WEST AND NORTH)

INSPECTION HELD ON 02.06.2017 BY THE COMMITTEE APPOINTED BY

THE HON'BLE HIGH COURT

1. Sahipur

(a) Khasra No. 4//28/2 (23-18)

The water body as, stated, by DDA staff as well as Revenue staff is encroached upon. It was also informed that demarcation order has been passed over by the Hon'ble Delhi High Court as told by the representatives about an year ago. Although order has been passed an year ago, as communicated, but demarcation is yet to be started. As agreed, date of carrying of demarcation is fixed on 9.6.2017 at 9:00 am. which shall continue till the same is completed.

Revenue and DDA officers to remain be present at site on 09.06.2017 as no further communication/information is required for this purpose.

As regard, existing water body is concerned, same is found in pathetic condition. Surrounding of said water body is also in the same position as junk is found lying over the surrounding of the water body. DDA is requested to clean the surrounding at the earliest. No one is present from

Engineering Department of DDA to let us know as to how the water would be collected in the water body and what are the catchment areas.

Pertinent to note that despite due information no one was present in the meetings of the water bodies conducted by the Court Commissioner, prior to their visit to know the exact position. No status report has also been placed before the Court Commissioner. Officer appears not to be serious and vigilant.

Demarcation report be submitted by 30.06.2017.





#### 2. Pooth Kalan

# (a) Khasra No. 30//24(4-9), 25(4-16), 41//4/2(0-14), 5(4-2), 42//1 (4-16) and 2(4-16) total area (23-13)

Water body has 5 ft. depth. Water is filled either through rain or tube well. Tube well is operating from 4.00 AM to 4.00 PM. There is no catchment of rain water from road found at spot. Rains are at the corner. Authorities should make arrangement for catchment of water from the road which is possible. Needful be done within 10 days. Report be submitted within 15 days. Tube well is operating from 4:00 am to 4:00 pm.





#### 3. Kirari & Kirari Suleman Nagar

#### (a) Khasra No. 1270 min (10-16)

Water body is in pathetic condition. Sewage is also flowing into the water body. Delhi Jal Board is directed to ensure that no sewage flows into the water body and should submit their plan immediately. It is also brought to our notice that scheme has already been prepared by I&FC Department and the same is pending before PDRD for more than a year. It is also brought to our notice that the scheme of other water bodies of Delhi are also pending before PDRD and no action has been taken by them for all the water bodies of Delhi since more than a year.

During the discussion at site it has also been brought to our notice that a nala is also as part of scheme for disposal of sewerage in to Mubarakpur Drain and the same is part of the scheme which is pending disposal at the end of PDRD.

Pertinent to note that despite information no one attended the meetings convened by Court Commissioner from PDRD Department. PDRD to take immediate action and submit the report to the Court Commissioner in maximum 20 days.





## (b) Khasra No. 966 (17-11)

Worst condition. Water is flooded on the roads and one could see children walking through the said dirty water. It was also reported that there was some encroachment. Accordingly demarcation is fixed for 9.6.2017 at 9:00 am. Report to be submitted by 25.6.2017.





#### 6. Jaunti

#### (a) Khasra No. 330/20min (14-16)

Encroachment is found about 2 bighas of the water body. It is brought to our notice that a request for demarcation was made to M/s INTECH in October 2016 where after reminders have also been sent but to no result. Demarcation is fixed for 6.6.2017 at 10:00 am as per telephonic confirmation by surveyor M/s Intech. Demarcation and marking be done within 10 days where after demolition process be undertaken within 10 days. Report be submit by 30.06.2017.





# (b) Khasra No. 255 (9-14)

Developed

# (c) Khasra No. 86//21/2(0-11) and 86//22/1(2-0) total area (2-11)

Developed

## (d) Khasra No. 225 (29-7)

Natural water body.





# (e) Khasra No. 28//7/2 (1-9)

Developed.





#### (f) Khasra No. 19//22(4-2) and 19//23(5-13) total area (9-15)

A case is reported to be pending before Financial Commissioner titled as "Sahib Singh Vs. Gram Sabha Jaunti". The BDO has assured that all the papers concerning the case would be sent to the Court Commissioner by Friday i.e. 09.06.2017. However no papers have been submitted till date.





## (g) Khasra No. 4//4/2 ((2-2)

MCD School exist at site. It was locked. The authorities should at least construct Rain Water Harvesting System.



### 5. Punjab Khore

#### (a) Khasra No. 515(19-17)

No catchment has been found in the existing water body. Plan/Scheme should be submitted by Monday and the project should be completed within 10 days. Water body should be cleaned within the said stipulated time. Re visit on 22/23.6.2017.



#### (b) Khasra No. 195/1(1-1)

It is Land Locked open land.

#### (c) Khasra No. 1340,1341,1342,1343 total area (7-1)

Community Centre exist on the spot. The authorities should atleast construct a Rain Water Harvesting System.



#### 6. Jat Khore

#### (a) Khasra No. 16//20(4-16)

Although it is developed but it is dry. The water Body needs to be cleaned and catchment of water from road should be constructed.





## (b) Jat Khore

## Khasra No. 17//24 min(1-13) total area (6-9)

Panchayat Ghar and Choupal exist. The authorities should atleast construct Rain Water Harvesting System.



#### (c) Jat Khore

## Khasra No. 32//7/1(4-8)

Although Water Body is developed but it is dry. Water Body needs to be cleaned. The same should be done immediately.



#### (d) Jat Khore

#### Khasra No. 35/16 & 35//25min(3-6) total area (7-14)

Though it is developed. However, there is no source of catchment. The water body is filled through tube well, as stated. The construction of the water body indicates that it is not well designed as there is no source of catchment. Explanation form the I&FC Department be called.



#### 7. Holambi Khurd

#### Khasra No. 117,118 total area (19-2)

The water body is encroached. The SDM representative in directed that demarcation has been carried out which was refused by the representative of BDO. The Villages also informed that they have written no. of letters for carrying out of demarcation and constructing of boundary wall around the Water Body. Chief Engineer (I&FC), BDO, SDM, MCD and Delhi Jal Board to attend the meeting to be held on 6.6.2017 at 5:00 PM in the office of Sh. V.K. Tandon, Court Commissioner, (M) 9810177733 at 31/26, East Patel Nagar, New Delhi-110008 alongwith relevant records.



(Arvind Sah)
Court Commissioner

(Vivek Kumar Tandon) Court Commissioner