

# VIVEK KUMAR TANDON

## ADVOCATE

**Chambers:**

404, Lawyers' Chambers, Delhi High Court Complex, Sher Shah Road, New Delhi-110003.  
529, Lawyers' Chambers, Western Wing (Criminal Side), Tis Hazari Courts, Delhi-110054.

**Residence-Cum-Office:**

31/26, East Patel Nagar, New Delhi-110008.  
Mobile – 98101-77733

**Phones:**

2338-4570  
2393-5290

**Tele-faxes:**

2585-0970  
2585-4970  
2578-9608

E-mail: [tandonadvocates@gmail.com](mailto:tandonadvocates@gmail.com)  
[vivekkumartandon@gmail.com](mailto:vivekkumartandon@gmail.com)

### MINUTES OF MEETING OF SITE INSPECTION HELD ON 17.12.2016 BY THE COMMITTEE APPOINTED BY THE HON'BLE HIGH COURT

#### 1. JNU

Natural Water Body is located inside the campus of JNU. Authorities informed that during rainy seasons the Water Body gets enough water. However it is dry. Area and Khasra No. to be provided by JNU authorities.



## 2. JNU

Another Natural Water Body is located inside the campus of JNU. It was wet. Area and Khasra No. to be provided by JNU authorities.





### 3. JNU

Third Natural water body located inside the campus of JNU. It was wet. Area and Khasra No. to be provided by JNU authorities.





**4. Mehrauli (Neela Hauz)**

It belongs to DDA although it is wet, however, dirty water was in the Water Body. It was also smelling. Direction was found given to clean the water body. Area and khasra no. to be provided by DDA.



**5. Mehrauli (Baba Adhrang Nath)**

**a. Kh. No. (NEW) – 1220 (13-3)-(OLD) - 2741, 2026, 1675**

It belongs to DDA. Same position as before. However authorities indicated that plans are underway. Proposed drawings to be submitted immediately before the Court Commissioner.





**6. Shayoorpur**

**a. Kh. No. 92 (9-1)**

It belongs to Forest Deptt. Water body is in very pathetic condition. It is converted into dumping ground. Dirty water was found in the water body. Nobody from Forest was present during the inspection.



## 7. Fatehpur Beri

### a. Kh. No. 691(6-8)

It belongs to BDO. Dirty water found in the water body. Garbage was found dumped into the water body. BDO to take necessary step to clean, develop and maintain the same. BDO is further directed to send the latest photograph after cleaning the Water Body within two weeks.





**8. Dera Mandi**

**a. Kh. No. 444(19-13)**

It belongs to BDO. The Water Body is found to be encroached. Demarcation to be done within 15 days and thereafter steps to remove the encroachment be undertaken immediately. Report be submitted by 31.01.2017 to the Court Commissioner.



(Arvind Sah)  
Court Commissioner

(Vivek Kumar Tandon)  
Court Commissioner