

DELHI PARKS AND GARDENS SOCIETY

(A Society Registered under the Societies Registration Act of XXI, 1860)
(Registration No. S/62922/2008)

DEPARTMENT OF ENVIRONMENT

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

"C" Wing, 6Th Level, Delhi Secretariat Building, I P Estate, New Delhi 110002

Tele-Fax: 011-23392736 E-mail ceodpgsenv.delhi@nic.in

F.No.- F1(01)/DPGS/WB/2012-13/


7665-77





Dated: 01/01/15

Prior to field inspection, the Court Commissioner called a meeting in his Ch. No. 404, Delhi High Court of various agencies on 18-12-2014 and 19.12.2014 in r/o Water Bodies. Visit of Distt. West was conducted on 20-12-2014. On the basis of field inspection of water bodies the detailed report of inspection of water bodies is submitted as follows:-


DISTRICT - WEST

DATE OF VISIT: 20.12.2014

1.	<u>Ranhola safipur ranhola:-</u>	
G. No. 905	Kh. No. 76(3-13) (3077 sq.mtrs.) It is dry water body of BDO. Community Centre and Barat Ghar exits on the water body area. Boundary wall has been completed. Court Commissioner directed that Rain Water Harvesting System to be installed.	

<p>2.</p> <p>G. No. 901</p>	<p><u>Nilothi:-</u></p> <p>Kh. No. 39//9/2(5-8)</p> <p>It is dry water body of BDO. Community centre exist on the water body area. Court Commissioner directed BDO to clean the catchment area and install rain water harvesting system.</p>	  <p>28°38.830'N 76°03.498'E Alt.- 101.3 m</p>
<p>3.</p> <p>G. No. 871</p>	<p><u>Hatsal (Patrly):-</u></p> <p>Kh. No. 55/13(4-14)14(2-9)16(4-10)17(6-2)18(5-4) total=(22-19)</p> <p>It belongs to BDO. It is wet. Sewage is flowing into the water body. Sh. Brij Kishore, AE (Maintenance) from MCD is present. Court Commissioner found that lot of garbage still lying in the johar despite clear direction of Hon'ble High Court. Court Commissioner directed to Sh. Brij Kishore, AE, MCD to convey the direction to the sanitation deptt. immediately. Gargabe bin be shifted immediately outside the johar area. Further I&FC is required to put barriers on both the entry point in order to avoid entry of trolleys/trucks carrying malba to avoid the same being dumped in the water body. Nobody is present from Delhi Jal Board.</p>	  <p>28°37.853'N 77°03.273'E Alt.- 101.3 m</p>

4.	<u>Nagli jalib:-</u>	
G. No. 902	Kh. No. (a)1 etc/70 (3-9) <p>The position of water body is not clear. Court Commissioner issued the direction to the DDA, MCD and Revenue Deptt. to clear the position of the water body.</p>	28°37.966'N 77°05.190'E Alt.- 101.3 m


(Dr. S. D. Singh)
 C.EQ-DPGS,
 Nodal officer, Water Bodies