

DELHI PARKS AND GARDENS SOCIETY

(A Society Registered under the Societies Registration Act of XXI, 1860)
(Registration No. S/62922/2008)

DEPARTMENT OF ENVIRONMENT

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

"C" Wing, 6th Level, Delhi Secretariat Building, I P Estate, New Delhi 110002

Tele-Fax: 011-23392736 E-mail ceodpgsenv.delhi@nic.in

F.No.- F1(05)/DPGS/WB/2016-17/ 4208-4221

Dated: 13/1/2017

Sub: Minutes of Meeting of Committee constituted on direction of Hon'ble NGT in the matter of "Diwan Singh Vs. Union of India & Ors." OA No. 299 of 2016 held on 6.1.2017 at 3:00 PM in the office of Chief Engineer (Dwarka), DDA, Manglapuri, New Delhi.

Sir,

Please find enclosed herewith copy of minutes of Committee constituted direction of Hon'ble NGT in the matter of "Diwan Singh Vs. Union of India & Ors." OA No. 299 of 2016 held on 6.1.2017 at 3:00 PM in the office of Chief Engineer (Dwarka), DDA, Manglapuri, New Delhi.

Encl: As above

To,

1. **Commissioner, SDMC, 9th Floor, Dr. SPM Civic Centre, Minto Road, Delhi- 02**
2. **Sh. S. Bhattacharya, Head of Office, SUO, Central Ground Water Board, State Unit Office, 18/11, Jamnagar House, New Delhi -110011**
3. **Dr. A.B. Akolkar, Member Secretary, Central Pollution Control Board, New Delhi**
4. **Sh. D.P. Singh, Chief Engineer (Dwarka), DDA, Mangla Puri, New Delhi - 110045**
5. **Dr. Arun Kumar, Assistant Professor, Civil Engineering Department, Indian Institute of Technology (IIT), Hauz Khas, New Delhi - 110016**
6. **Sh. V.K. Gupta, Chief Engineer (Dr) P- I, DJB, Varunalaya, Phase-II, Jhandewalan, Karol Bagh, New Delhi - 110005**
7. **Chief Engineer -I&FC (Zone -1), LM Bund Office Complex, Shastri Nagar, Delhi - 31**
8. **SDM (Dwarka), Old Terminal Tax Building, Kapashera, New Delhi- 110037**
9. **BDO (South West), Najafgarh, New Roshanpura, New Delhi - 110043**


(Dr. S.D. Singh)

CEO-DPGS, Nodal officer, Water Bodies

Copy for information and necessary action to:-

1. Divisional Commissioner, Revenue Deptt., GNCTD, 5, Sham Nath Marg, Delhi-54
2. VC, DDA, 1st floor, 'B' Block, Vikas Sadan, INA, New Delhi - 110023
3. Distt. Magistrate (South West), Old Terminal Tax Building, Kapashera, N. Delhi - 37
4. CEO, Delhi Jal Board, Phase-II, Jhandewalan, Karol Bagh, New Delhi -05
5. SE/Nodal Officer, Water Bodies-CC-13, DDA, Dwarka, Near Manglapuri, N. Delhi-30
6. PS to Secretary (Env. & Forest), GNCT of Delhi


Dr. S.D. Singh)

CEO-DPGS, Nodal officer, Water Bodies

DELHI PARKS AND GARDENS SOCIETY

(A Society Registered under the Societies Registration Act of XXI, 1860)
(Registration No. S/62922/2008)

DEPARTMENT OF ENVIRONMENT

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

"C" Wing, 6th Level, Delhi Secretariat Building, I P Estate, New Delhi - 110002

Tele-Fax: 011-23392736 E-mail ceodpgsenv.delhi@nic.in

F.No.- F1(05)/DPGS/WB/2016-17/ 4208-4221

Dated: 13/1/2017

MINUTES OF MEETING

In order to review the progress regarding revival/development of water bodies of Dwarka by the Committee constituted on direction of Hon'ble National Green Tribunal in OA No. 299 of 2016 titled as "Diwan Singh & ANR Vs. Union of India & Ors., a meeting was held in the office of Chief Engineer (Dwarka), DDA on 6.01.2017 at 3:00 PM.

List of participants is at Annexure-I.

1. This is with reference to the Hon'ble National Green Tribunal direction dated 1.11.2016 as per which a team was constituted by Hon'ble NGT to monitor the progress of identification, documentation, revival and monitoring of water bodies in Dwarka.
2. In this connection site inspection of Water Bodies of Dwarka was conducted by the Committee on 29.11.2016, 30.11.2016 and 2.12.2016.
3. A tentative report was made of each water body, inspected at site and observations made based on available records. A meeting was convened to discuss the inspection report on 6.1.2017 at 3:00 pm in the office of Chief Engineer (Dwarka), DDA with all the concerned field officers of DDA, MCD, IIT, DJB, CPCB etc. However officers from revenue department were not present.

4. During meeting the following issues of water bodies referred in the case and inspected have been discussed:-

1) Bamnoli, Kh. No. 232 (earlier 547) (4-15) - DDA

G. No. 602

Direction were given to stop sewage flowing into the water body and cleaning of its water. Repair of boundary wall, cleaning of the waste/debris/garbage from the water body. Plantation along boundary wall.

2) Bamnoli, Kh. No. 28/5 (4-6) - DDA

G. No. 603

Water body has been converted into dumping ground along its side. Encroachment exists at site. Garbage/waste is also found in the water body. Path has been converted to road by earth filling on one side of the water body. Direction were given to DDA to clean the water body and prevent dumping. The area of the water body restored as per record. Chief Engineer (Dwarka), DDA informed that there is a Court Case on part of water body area. Direction has been given to bring the Court Case before the Court Commissioner and Hon'ble NGT.

3) Bharthal, Khasra No. and area to be provided by DDA.

Chief Engineer (Dwarka), DDA informed that this is not a natural water body but depression exist. Direction has been given to keep this area as green. Khasra No. and area to be provided by DDA.

4) Bharthal, Kh. No. 184 (15-18) - MCD

G. No. 588

It has been transferred to MCD and has Dada Mota Mandir in it. Most of its area is constructed in concrete. There is very little plantation. Direction has been given to DDA to conduct TSM survey so that boundary wall to be identified.

5) Bharthal, Kh. No. 52/10/3(2-8) - DDA/Northern Railways

G. No. 589

DDA officials reported that it is transferred to Northern Railways. DDA was asked to write to Railways to maintain it. It is wet with clean water and have birds. It needs planting around its sides and TSM survey.

6) Bharthal, Kh. No. 147 (7-17) & 148 (0-1) Total area (7-18)- DDA

G. No. 590

The Community Centre and the Park exist at site which were in a pathetic condition. Malba was also found dumped in the park adjoining the Community Centre at various places. Further there was no boundary wall on two sides, from where chances of encroachment cannot be ruled out. Direction has been given to DDA to restore the total area of the water body after TSM survey followed by removal of encroachments and malba. Rain water harvesting system to be installed. Chief Engineer (Dwarka), DDA will examine. Plantation has to be done. Ornamental plants and tree species to be planted. DDA to put recharging pit. Gate is to be installed.

7) Bharthal, Kh. No. and area to be provided by DDA

It is located at Sector-24, Dwarka. According to DDA there is no water body. Directions have been given to DDA to provide Khasra Number alongwith area as well as old records of the area and also plan for the site.

8) Pochanpur, Kh. No. 26/26 (11-17) - DDA

G. No. 800

It is located at Sector-23, Dwarka. It is situated along special drain (Trunk Drain II). Direction has been given to DDA to divert rain water from adjoining plots of DDA land. Plantation along sides. It needs cleaning of grass and other waste from the site as well as deepening of water body area.

9) Pochanpur, Kh. No. 34 (7-6) - DDA

G. No. 802

It is located at Sector-23, Dwarka. It is seasonally wet. Boundary wall has been built up. Pacca path has been made around the pond. Directions have been given to DDA to plant trees around the water body.

10) Dhoolsiras, Kh. No. and area to be provided by DDA

It is located behind Shamshan Ghat. Green area with mostly Kikar plants exist around the Water Body. Directions have been given to DDA to provide Khasra Number alongwith total area of the water body and total area of the green belt. Also direction were given to maintain it as green belt along with water body.

11) Dhoolsiras, Kh. No. 72/2 (8-9) - DDA

G. No. 636

DDA officials informed that this water body has been transferred to BDO. However nobody is present from revenue and BDO office. BDO to confirm.

The water body has been converted into a dumping yard. It is partly encroached from sides. It has waste water from adjoining houses. Directions have been given to DDA to write to BDO to make boundary wall around the water body. Immediate measure needs to be taken to stop dumping immediately which is going on in the water body continuously.

12) Dhool Siras, Kh. No. 85 (7-13) - DDA

G. No. 637

It is wet with fairly clean water but waste paper/polythene found in water on the sides. Boundary wall is broken at some point. Direction has been given to DDA to clean water from waste dumping. Repair of boundary wall and bush cleaning.

13) Dhool Siras, Kh. No. 245 (0-14) - DDA

G. No. 638

DDA officials informed that this water body has been transferred to BDO. However nobody is present from revenue and BDO office. BDO needs to confirm the ownership status of this water body.

Direction has been given to DDA to write BDO to prevent dumping of garbage and other construction waste materials found at the site. The same needs immediate protection.

14) Dhool Siras, Kh. No. and area to be provided by DDA

DDA officials informed that it is a commercial land given to DLF. It was dug up for basement which shows depression at site. Direction has been given to DDA to provide land acquisition status and Khasra Number.

15) Bagdola, Kh. No. and area to be provided by DDA

DDA officials informed that in 1989-90 it was low a lying area. Direction has been given to DDA to maintain it as a green area. Malba has to be removed. It will remain as green area with trees. TSM survey is not required.

16) Bagdola, Kh. No. and area to be provided by DDA

This water body is situated at C-Block, Sector-8, Bagdola Village. It is seasonally wet. It is along drain hence rain water can be diverted toward it.

Direction has been given to DDA to provide details of the area alongwith Khasra Number of the water body as per records. It needs gate. Dumped waste and the Bushes need to be removed. Boundary wall needs repair. Plantation be done on its side

17) Bagdola, Kh. No. 31/204 (12 bigha) i.e. 2.4 acre

G. No. 927

DDA officials informed that this water body has been transferred to SDMC. It needs deepening and draining adjoining rain water towards recharging pit.

18) Bagdola, Kh. No. 1/157 (12-4) - DDA

G. No. 925

Direction has been given to DDA to clean the water body from waste and repair the boundary wall. Boundary wall can be shifted towards road to increase the area of water body. It needs cleaning outside area of water body.

19) Bagdola, Kh. No. 40/1(13-9) - DDA

G. No. 928

DDA officials informed that this water body has been transferred to SDMC on 27.5.16. Direction has been given to SDMC for deepening of water body area. Plantation in park be done. No further Pukka structure be made in water body area. RWH from adjoining Building be diverted and rain water towards this water body be carried out.

20) Palam, Kh. No. 155 (28-5) - DDA

G. No. 795

It has been transferred to SDMC. It is dry. Ground water level is very deep. Direction has been given to MCD to do TSM survey. RWH system from adjoining building. Removal of solid waste dumps and mud at site be done alongwith deepening in the middle.

21) Palam, Kh. No. 123 (20-15) - DDA

G. No. 792

DDA officials informed that this water body has been transferred to SDMC. It is seasonally wet and is along MCD drain. It is partially encroached.

Direction has been given to do TSM survey. It requires deepening. Plantation to be done. RWH from adjoining buildings be made along with removal of encroachment.

22) Palam, Kh. No. 122 (21-12) - DDA

G. No. 794

Direction has been given to DDA to provide details of Court Case pending before High Court and Dwarka Court.

23) Palam, Kh. No. 153 (13-10) - DDA

G. No. 793

DDA officials informed that this water body has been transferred to SDMC. Direction has been given to do plantation around the water body. It does not require TSM survey.

24) Amberhai (Earlier-Pochanpur), Kh. No. and area to be provided by DDA

Direction has been given to DDA to provide land status at the time of acquisition. Kh. No. to be provided. Chief Engineer (Dwarka), DDA informed that there is no water at the time of acquisition. It is to be maintained as green as per landscape planning of the site.

25) Amberhai (Earlier Pochanpur):- Chhattar Ka Johar, Kh. No. and area to be provided by DDA

Sh. Diwan Singh has stated in his list that this land is called as "Chattar ka Johar" but according to DDA as well as Revenue Deptt. there is no water body exist here.

Direction has been given to DDA to provide land status at the time of acquisition. Kh. No. to be provided. Chief Engineer (Dwarka), DDA informed

that there was no water at the time of acquisition. Direction has been given at site to be maintained as green as per DDA planning.

26) Amberhai, Kh. No. and area to be provided by DDA

It is a natural water body and is located in green area of DDA at District Park, Sector – 23, Dwarka. It is wet. It is located near drain hence can be joined with it for having water. A low depression exist near to it. Hence some pipe connectivity for water flow be provided between these two water bodies within the District park.

27) Amberhai, Kh. No. 57 (7-0) – DDA

G. No. 584

It is located along Drain and is seasonally wet. Waste Dump was found in the Water Body. Direction has been given to DDA to get the Water Body cleaned immediately. Boundary wall needs repair. Trimming and weed removal is required. Plantation. Rain water harvesting from adjoining building be done.

28) Amberhai, Kh. No. 38/10 (4-16) – DDA

G. No. 585

It is along drain. The water body is on the road side and waste dumping area. Direction has been given to DDA to plant more trees around the boundary wall of water body. TSM survey is not required. Cleaning of water body area from waste be carried out.

29) Amberhai, Kh. No. and area to be provided by DDA

It is low lying area and seasonally wet. It is located in District Park, Sector-19 B, Dwarka. It is under high tension line near Sports Complex site. It is total green area with small depression in the middle.

Direction has been given to DDA to provide Khasra Number along with area of the water body. Deepening is not required.

30) Amberhai, Kh. No. to be provided by DDA

DDA reported that it is not a water body. Kh. No. and area to be provided by DDA. It is green area but no sign of water body. DDA was directed to make it green with trees.

31) Nasirpur, Kh. No. 109 (Area- 6782 Sq. Mtr.) (12-14), 724/379 (1 Min)- 0.18 and 111- 0.04 - DDA

G. No. 772

Twin water bodies exist at site. Direction has been given to DDA to bring Court case before Court Commissioner and Hon'ble NGT. TSM survey to be done. Cleaning and removal of debris. Removal of encroachments. Associate RWA for encroachments removal and management. Repair boundary wall and plantation with tree species be carried out.

32) Nasirpur, Kh. No. 612/2 (11-19) - DDA

G. No. 768

It is partly dry and partly wet with dirty water near to drain. It is under encroachments having paper boards industry. It is under Court case. Direction has been given to DDA to bring Court case before Court Commissioner and Hon'ble NGT. TSM survey is to be done as well as removing encroachments.

33) Dwarka, Sector-5, DDA Office Complex, Kh. No. and area to be provided by DDA

It is located in Sector-5, DDA office Complex in an about 1 acre. According to DDA, there is no water body exist here. However they are maintaining it

as low lying area and has water during rainy season. Direction has been given to DDA to do plantation. Arjun, Jamun trees to be planted.

34) Kakrola, Kh. No. 184 (15-6) - DDA

G. No. 692

Direction has been given to DDA to do TSM survey. To bring Court case before Court Commissioner and Hon'ble NGT. Removal of solid waste dumping and weeds from water body area. RWH from adjoining building. Repair of boundary wall. Plantation around its boundary.

35) Kakrola, Kh. No. 194 (15-4) - DDA

G. No. 693

It is located along drain. It is wet at present. Temple is in existence on the land of water body. Its boundary wall is broken. Direction has been given for Cleaning of debris and other waste from site as well as repair of boundary wall and plantation.

36) Kakrola, Kh. No. 192 (8-17) - DDA

G. No. 692

It is situated along MCD drain. It is wet but has sewage and industrial waste as well as acid is being dumped on the water body land. Encroachment exist as per TSM survey done earlier. Water body has been converted into dumping yard.

Direction has been given to DDA to stop sewage and industrial waste, and other chemical effluents being flowing into the water body. Immediate steps to remove encroachment. Tree plantation. Boundary wall making without any delay. Weed removal.

37) Kakrola, Kh. No. 175 (17-10) - DDA

G. No. 695

It is an encroached area. Direction has been given to DDA for TSM survey and carryout plantation and removal of encroachments.

38) Kakrola, Kh. No. 195/41(1-9) - DDA

G. No. 693

It is converted into building area as Panchayat Bhawan. It is known as Suraj Kund. Direction has been given for Rain water harvesting plantation along boundaries.

39) Kakrola, Kh. No. 14/20/2(1-8) - DDA

G. No. 694

It is located along road and has temple made at site. It needs TSM survey. Also needs proper boundary wall and tree plantation. Debris needs to be removed from the site.

40) Luharheri, Kh. No. 4/26 (3-11) - DDA

G. No. 732

DDA officials informed that this water body has been transferred to ASI a baoli exists at site. This area is under green belt and is located between Gangotri Apartment and Dwarka International School. Direction has been given to DDA to write a letter to ASI to maintain it. SDMC is directed divert its water drain and Road No. 202 drain water towards it.

41) Toganpur, Kh. No. 1/183(12-2) - DDA

G. No. 839

It is a natural water body and is located in forest area of DDA. It is located at Bharat Vandana Udhaan, Sector-20, Dwarka, measuring 1 Km X 1 Km green area. Direction has been given to DDA to tender for maintenance and develop it as a bio diversity park.

42) Shahbad Mohd. Pur, Kh. No. 1/72 (28-13) - DDA

G. No. 983

The water body belongs to DDA next to Railway crossing. The people of the village indicated that the said water body used to be filled with water. However it was dry during visit. No catchment of water body was also found. DDA was directed to look into the matter, take remedial measure and submit the report within three weeks. Gate to be installed.

43) Shahbad Mohd. Pur, Kh. No. 1/535 (31-6) - DDA

G. No. 984

At site park exists. Direction has been given to make recharging pits at corners and plantation around the water body area.

Apart from above directions as well as direction in the draft report, following needs to be carried out:-

1. Proper map of each water body be made with planned landscape and submit to this office in a week time.
2. Every month, monitoring report of field inspection/sites of each water body be carried out in the last week of the month and be submitted to this office within a week of inspection.
3. Next meeting will be held within a fortnight to review the status of action taken.



(Dr. S.D. Singh)
CEO-DPGS,

Nodal officer, Water Bodies