

**DELHI PARKS AND GARDENS SOCIETY**

(A Society Registered under the Societies Registration Act of XXI, 1860)  
(Registration No. S/62922/2008)

**DEPARTMENT OF ENVIRONMENT**

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

"C" Wing, 6<sup>th</sup> Level, Delhi Secretariat Building, I P Estate, New Delhi 110002

Tele-Fax: 011-23392736 E-mail ceodpgsenv.delhi@nic.in

F.No.- F1(05)/DPGS/WB/2016-17/ 589-609

Dated: 13/6/2017

**Sub: Minutes of Meeting of Committee constituted on direction of Hon'ble NGT in the matter of "Diwan Singh Vs. Union of India & Ors." OA No. 299 of 2016 held on 08.06.2017 at 3:00 PM in the office CEO, DPGS, Deptt. of Environment, New Delhi.**

Sir,

Please find enclosed herewith copy of minutes of meeting held on 8.6.2017 at 3:00 PM in the matter of "Diwan Singh Vs. Union of India & Ors." OA No. 299 of 2016 in the office of CEO, DPGS, Department of Environment, C Wing, 6<sup>th</sup> Level, Delhi Secretariat Building, New Delhi - 110002.

You are therefore requested to take action for revival/development of water bodies as decided in the meeting. It is also decided in the meeting that the next inspection of all the water bodies of Dwarka will be conducted on **15.6.2017 and 16.6.2017 from 9:00 am onwards.**

It is requested to make it convenient to attend the site inspection on **15.6.2017 and 16.6.2017 at 9:00 AM.** The assemble point is **office of Chief Engineer (Dwarka), DDA, Mangla Puri, New Delhi -45 at 9:00 AM sharp.**

**Encl: As above**

To,

1. **Distt. Magistrate (South West)**, Old Terminal Tax Building, Kapashera, N. Delhi - 37
2. **Distt. Magistrate (New Delhi)**, 12/1, Jam Nagar House, Sahajahan Road, N. D - 110011
3. **Commissioner, SDMC**, 9<sup>th</sup> Floor, Dr. SPM Civic Centre, Minto Road, Delhi- 02
4. **Sh. S. Bhattacharya, Head of Office, SUO**, Central Ground Water Board, State Unit Office, 18/11, Jamnagar House, New Delhi -110011
5. **Dr. A.B. Akolkar, Member Secretary**, Central Pollution Control Board, New Delhi
6. **Sh. Sachidanand Singh, Chief Engineer (Dwarka), DDA**, Mangla Puri, New Delhi -45
7. **Dr. Arun Kumar, Assistant Professor**, Civil Engineering Department, Indian Institute of Technology (IIT), Hauz Khas, New Delhi - 110016
8. **Sh. V.K. Gupta, Chief Engineer (Dr) P- I, DJB**, Varunalaya, Phase-II, Jhandewalan, Karol Bagh, New Delhi - 110005
9. **Chief Engineer -I&FC (Zone -1)**, LM Bund Office Complex, Shastri Nagar, Delhi - 31
10. **SDM (Dwarka)**, Old Terminal Tax Building, Kapashera, New Delhi- 110037
11. **SE/Nodal Officer, Water Bodies-CC-13, DDA**, Dwarka, Near Manglapuri, N. Delhi-30
12. **SE (Lab)/Nodal Officer, Water Bodies, SDMC**, Technical Lab, Alipur Road, Delhi -54
13. **Dy. Director (Land Management) West Zone, DDA**, Subash Nagar Xing, New Delhi-18
14. **Dy. Director (Hort.)**, Div. Dwarka, DDA, Central Nursery, Sector-5, Dwarka, N.D- 75
15. **BDO (South West)**, Najafgarh, New Roshanpura, New Delhi - 110043
16. **BDO (New Delhi)**, Najafgarh, New Roshanpura, New Delhi - 110043

  
(Dr. S.D. Singh)

CEO-DPGS, Nodal officer, Water Bodies

**Copy for information and necessary action to:-**

1. Divisional Commissioner, Revenue Deptt., GNCTD, 5, Sham Nath Marg, Delhi-54
2. VC, DDA, 1st floor, 'B' Block, Vikas Sadan, INA, New Delhi - 110023
3. CEO, Delhi Jal Board, Phase-II, Jhandewalan, Karol Bagh, New Delhi -05
4. Sh. Richhpal Singh, HA, is hereby directed to attend the site inspection.
5. PS to Secretary (Env. & Forest), GNCT of Delhi



**(Dr. S.D. Singh)**

CEO-DPGS, Nodal officer, Water Bodies



# DELHI PARKS AND GARDENS SOCIETY

(A Society Registered under the Societies Registration Act of XXI, 1860)  
(Registration No. S/62922/2008)

## DEPARTMENT OF ENVIRONMENT

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

"C" Wing, 6<sup>th</sup> Level, Delhi Secretariat Building, I P Estate, New Delhi - 110002

Tele-Fax: 011-23392736 E-mail ceodpgsenv.delhi@nic.in

F.No.- F1(05)/DPGS/WB/2016-17/ 589-609

Dated: 13/6/2017

### MINUTES OF MEETING

In order to review the progress regarding revival/development of water bodies of Dwarka by the Committee constituted on direction of Hon'ble National Green Tribunal in OA No. 299 of 2016 titled as "Diwan Singh & ANR Vs. Union of India & Ors., a meeting was held in the office of CEO, DPGS on 8.6.2017 at 3:00 PM.

**List of participants is at Annexure-I.**

Discussion as held as follows:-

**1) Bamnoli, Kh. No. 232 (earlier 547) (4-15) - DDA**

**G. No. 602**

Officers from DDA submitted that repair of boundary wall and cleaning of water body have been completed. Plantation shall be taken up with the onset of monsoon. DJB has reported that local residents are forcing not to stop the diversion of waste water into the water body with the assertion that it is water from washing/bathing etc. But at the time of inspection it was observed that it is waste water entering into the wet land which should not take place. Delhi Jal Board either has to divert waste water so that it should not enter in to the water body or follow some alternatives to have clean water flow in to the water body. DJB was directed to do the needful. Plantation to be done in the Monsoon by DDA.

**2) Bamnoli, Kh. No. 28/5 (4-6) - DDA**

**G. No. 603**

Officer from DDA submitted that dumping of garbage near water body is to be stopped by SDMC. SDMC shall look into the matter and should take care of further no dumping. Dumped waste is to be removed in a week time by DDA. Part of Boundary wall has been constructed by DDA wherever feasible. Due to some difficulties boundary wall could not be constructed in whole length. Further DDA submitted that details of court case shall be provided in a week time. Plantation should be done by DDA in coming Monsoon.

**3) Bamnoli, Kh. No. 23/1(Min) & 10 (Min), 8/24 (Min) & 25 (Min), 22/4(Min), 22/5(Min), 22/6(Min), 22/7(Min) (Area – 2.59 hac.) - DDA**

Khasra No. and area has been provided by DDA. Earlier it was assumed in Village Bharthal but infact it is in Bamnoli Village. Officers from DDA submitted that total station survey (TSM) of the Water Body has been sent to Director (Landscape), DDA for preparing landscape plan which is awaited. It is not a natural water body, however, Khasra Number of this low lying area are 23/1(Min) & 10 (Min), 8/24 (Min) & 25 (Min), 22/4(Min), 22/5(Min), 22/6(Min), 22/7(Min) of Village Bamnoli. Total low lying area is 2.59 hac. Directions were given to make a complete landscape plan. Tree plantation to be done this Monsoon along boundary. Revenue Deptt. has been directed to record it as water body. It should be linked to adjoining drain.

**4) Bharthal, Kh. No. 184 (15-18) - MCD (South)**

**G. No. 588**

A temple exists on its side in the area of water body. In the meeting held on 20.4.2017, directions were given to Revenue Deptt. to conduct TSM survey so that boundaries to be identified. It is to be done on an emergent basis. SDMC was earlier directed to submit action taken report by 30.4.2017 but no action taken report has been received till date. Cleaning of water body to be done in a week time. Plantation to be done in the coming Monsoon.

**5) Bharthal, Kh. No. 52/10/3(2-8) – DDA/Northern Railways**

**G. No. 589**

DDA officials reported that they have requested Divisional Manager of Northern Railways vide letter No CE(DWK)26(67)/NGT/787 dt 16.02.17 to take up the development of the water body. Directions were given to DDA to conduct TSM survey. DDA is to get the progress from Northern Railways. DDA to get the plantation done through Northern Railways or by DDA itself this Monsoon. It is wet water body with clean water and be maintain as such.

**6) Bharthal, Kh. No. 147 (7-17) & 148 (0-1) Total area (7-18)- DDA**

**G. No. 590**

Officers from DDA submitted that debris/malba has been removed. Tenders for rain harvesting/recharging pits are under process and work shall be completed by 30.09.2017. Tree plantation to be done by DDA this Monsoon.

**7) Bharthal, Lat/Long: 28° 33' 427' N, 77°02.260' E**

**Kh. No. and area to be provided by DDA**

Joint inspection has been carried out on dated 23.02.2017 alongwith DDA officials, wherein according to DDA, there is no water body exist both in records and at site. Lets DDA provide status of this land at the time of acquisition. As per appearance it is not deep, just small depression at the middle exist. DDA to provide Khasra Number for this land. No cooperation is obtained from Land Management of DDA. DDA has reported during meeting that it is meant for building in its planning records.

**8) Pochanpur, Kh. No. 26/26 (11-17) – MCD (South)**

**G. No. 800**

It is located at Sector-23, Dwarka. It is situated along special drain (Trunk Drain II). Directions were given to SDMC to clean the water body and to divert nearby drain water into this water body without delay so that rain

water flowing through drain enters into it. Plantation to be done in coming Monsoon.

**9) Pochanpur, Kh. No. 34 (7-6) - DDA**

**G. No. 802**

Officers from DDA submitted that Deputy Director (Horticulture) has been directed for planting more trees around the water body.

**10) Dhoolsiras, Lat/Long: 28° 33' 391' N, 77°02.061' E**

**Kh. No. and area to be provided by DDA**

It is located behind Shamshan Ghat. Officers from DDA submitted that this water body has been fenced properly and area shall be maintained as green with water body. Directions were given to DDA to provide Khasra Number alongwith total area and map of the water body in a week time. It should be connected with adjoining Airport drain. Also provisions be made to bring the rain water from adjoining roads in to the water body.

**11) Dhoolsiras, Kh. No. 72/2 (8-9) - BDO**

**G. No. 636**

BDO ietter No. 232 dated 31.5.2017 addressed to Superintending Engineer, Civil Circle -13, DDA, Manglapuri, New Delhi - 110045 has been received from BDO (South West) stating that this water body does not belongs to BDO and it was wrongly stated by DDA that the water bodies of Village Dhoolsiras have been transferred to BDO (Copy attached). As per the ATR submitted by DDA the water body is in possession of BDO. However, No one is present from BDO office. Till situation is not clear, DDA was directed to clean the water body in a week time. Plantation is to be carried out in the coming monsoon by DDA. Removal of encroachment is also be done by DDA along with repair of boundary wall in a month time.

**12) Dhool Siras, Kh. No. 85 (7-13) - DDA**

**G. No. 637**

Boundary wall has been repaired by DDA. Cleaning has also been done. Plantation is to be done during coming monsoon.

**13) Dhool Siras, Kh. No. 245 (0-14) - BDO**

**G. No. 638**

Letter No. 232 dated 31.5.2017 addressed to Superintending Engineer, Civil Circle -13, DDA, Manglapuri, New Delhi - 110045 has been received from BDO (South West) stating that this water body does not belongs to BDO and it was wrongly stated by DDA that the water bodies of Village Dhoolsiras have been transferred to BDO. As per the ATR submitted by DDA the water body is in possession of BDO. However, No one is present from BDO office.

It is a very small piece of land between the village abadi. DDA is to do plantation in the coming monsoon and the water body.

**14) Dhool Siras, Lat/Long: 28° 33' 635" N, 77°01.905" E**

**Kh. No. and area to be provided by DDA.**

As per the ATR submitted by DDA, it was agriculture land and never a water body. Now, its land use is commercial. This plot was handed over to DLF for construction of an Hotel, however, the project could not materialized till date. DDA was directed to provide Khasra No. and area of the site.

**15) Bagdola, Lat/Long: 28° 34.445' N, 77° 04.065' E (Distt. New Delhi)**

**Kh. No. and area to be provided by DDA.**

It is known as Mansa Devi area, a very small piece of land. As per the ATR submitted by DDA, It will be maintained as a green and malba shall be removed up to 30.06.2017. However, it is not a water body and should be deleted from the list. Directions were given to DDA to provide Khasra

Number alongwith area of the water body at the time aquisition. Measurement of area to be done in a week time. Plantation to be done by DDA in the coming monsoon with ecologically suited tree species.

- 16) Bagdola, Lat/Long: 28° 34.215' N, 77° 04.602' E (Distt. New Delhi)**  
**Kh. No. and area to be provided by DDA in a week time.**

This water body is situated at C-Block, Sector-8, Bagdola Village. Its map and area along with Khasra No. is to be given by DDA in a week time. As per the ATR submitted by DDA, plantation shall be done with the onset of monsoons. DDA has reported that removal of debris be completed in a fortnight along other kind of waste. Boundary to be repaired in a month time.

- 17) Bagdola, Kh. No. 31 (12 bigha) i.e. 2.4 acre - SDMC**  
**G. No. 927**

Directions were given to SDMC to clean the water body within one week. Adjoining drain water is to be diverted into it for recharging in a week time. Plantation to be done in coming raining season. DDA was asked to provide Map to MCD and this office in a week time.

- 18) Bagdola, Kh. No. 1/157 (12-4) - DDA**  
**G. No. 925**

Direction were given to DDA to clean the waste from the water body within one week and repair the boundary wall in 15 days time. Officials from DDA submitted that plantation shall be done before onset of monsoons and cleaning and repair of boundary wall shall be completed by 30.06.2017.

- 19) Bagdola, Kh. No. 40/1(13-9) - MCD (South)**  
**G. No. 928**

Direction has been given to MCD (South) for deepening of water body area. Tree plantation in vacant land be done during monsoon season. Rain water



from adjoining drain be diverted towards this water body by MCD within a week time.

**20) Palam, Kh. No. 155 (28-5) - MCD (South)**

**G. No. 795**

As per ATR submitted by DDA it belongs to MCD. Direction were given to MCD to remove dumped waste within one week time. It is yet to be done. Plantation to be done during monsoon season. Drain adjoining to it be joined for recharging.

**21) Palam, Kh. No. 123 (20-15) - MCD (South)**

**G. No. 792**

It is near Ramphal Chowk, Dwarka. Direction were given to MCD (South) to clean the water body and removal of encroachment be done without any further delay. Plantation to be done during monsoon season. It should be connected to adjoining drain in a week time by MCD.

**22) Palam, Kh. No. 122 (21-12) - DDA**

**G. No. 794**

It is reported by DDA that at the time of handing over to DDA by BDO, its area was about 4 bigha only. Rest was allotted by BDO weaker's section housing scheme prior to handing over to DDA. SDM and Tehsildar were asked to enquire into the matter and report in a 15 days time. As per the ATR submitted by DDA, plantation shall be done in the coming rainy seasons. One of the court case was decided in favour of DDA. Encroachment to that extent has been removed. The area of about 4 bigha is free from encroachment. The constructions on the balance area are existing before 2000 and are protected under provisions of Special Act in this regard. Directions were given to DDA to clean the water body. Directions were given to Horticulture Department of DDA for plantation during monsoon season. Another Court Case is yet to be decided. Gate will be repaired in 15 days time as assured by DDA.

**23) Palam, Kh. No. 153 (13-10) - MCD (South)**

**G. No. 793**

Direction were given to MCD (South) to stop unauthorized dumping and no further dumping be done in the water body. Plantation to be done around the water body in coming monsoon.

**24) Amberhai (Earlier-Pochanpur), Lat/Long: 28°34.100' N, 77°02.741' E  
Kh. No. and area to be provided by DDA**

This was agriculture land and it is not a water body. As per planning record, it is a residential area. Directions were given to DDA to provide Khasra Number alongwith area. Sufficient tree plantation to be done at site.

**25) Amberhai (Earlier Pochanpur):- Chhattar Ka Johar,  
Lat/Long: 28° 34' 237" N, 77°02.621" E**

As per the ATR submitted by DDA, this is not a water body and should be deleted from the list. There is a case by the petitioner before NGT, where it was submitted by DDA that there is no such water body named Chhattar ka Johar. DDA has taken up construction of HIG flats in this area. Directions were given to DDA to provide Khasra Number alongwith area in a week time. Revenue Deptt. was also asked to find out its status at the time of acquisition from their records for the site. Sufficient tree plantation be carried out in the planned area.

**26) Pochanpur, Kh. No. 33 (5-10)**

It has twin natural water bodies and are located in green area of DDA at District Park, Sector – 23, Dwarka. As per the ATR submitted by DDA it is existing in Khasra No. 33 (5-10) of village Pochanpur. It is properly maintained. Directions were given to DDA to provide total area of park

also. Delhi Jal Board was directed to work for water augmentation into the water bodies from adjoining drains and other sources. Tree plantation is to be carried out during this monsoon. DJB has informed that tendering is in progress.

**27) Amberhai, Kh. No. 57 (7-0) – DDA**

**G. No. 584**

DDA officials informed that cleaning of water body has been completed and boundary wall repaired. Plantation shall be done during rainy season.

**28) Amberhai, Kh. No. 38/10 (4-16) – DDA**

**G. No. 585**

DDA officials informed that cleaning of water body has been completed and plantation shall be done during rainy season

**29) Amberhai, Kh. No. 14/11 Min, 14/12 Min - DDA**

It is low lying area and seasonally wet. It is located in District Park, Sector-19 B, Dwarka. It is under high tension line near Sports Complex site. As per the ATR submitted by DDA it is existing in Khasra No. 14/11 Min, 14/12 Min of village Amberhai and is part of District Greens. Revenue Deptt. was asked to trace the areas of these Khasra Nos. and record it as water body in a week time. Plantation shall be done by DDA during coming monsoon season.

**30) Amberhai, Kh. No. 35/7 Min - DDA**

It is located behind DCP (South West) Office, Sector-19, District Park in front of CNG/Petrol Pump. As per the ATR submitted by DDA it is existing in Khasra No. 35/7 Min of village Amberhai of District Park behind DCP (South West) office Sector -19, Dwarka, a low lying depression in green area. Revenue Deptt. was asked to trace out area of the Khasra Nos. and

record it as water body in revenue records. More plantation shall be done before rainy season.

**31) Nasirpur, Kh. No. 109 (Area- 6782 Sq. Mtr.) (12-14), 724/379 (1 Min)- 0.18 and 111- 0.04 (13-16) - DDA**

**G. No. 772**

Twin water bodies exist at site.. As per the ATR submitted by DDA more plantation shall be done before rainy season. Copy of drawing has been provided. Boundary wall has been repaired and additional plantation shall be taken up in the coming monsoon. Small encroachments exists which needs to be removed in a month time. Direction were given to DDA to bring Court case before Court Commissioner and Hon'ble NGT.

**32) Nasirpur, Kh. No. 612/2 (11-19) - DDA**

**G. No. 768**

It is partly dry and partly wet with dirty water. A drain adjoining to it has waste water also makes it filled with dirty water. It is under encroachments having paper board industry and its waste water also enters in to it. It is under Court case. As per the ATR submitted by DDA, more plantation shall be done before rainy season. TSM survey is not feasible due to resistance from the local residents, who are party in the court case. However, Revenue Deptt. must explore the possibility of doing TSM survey. DDA will assist. Directions were given to DDA to get the demarcation done with help of Revenue Deptt. in 15 days by writing a letter to Revenue Deptt. Revenue Deptt. will raise the bill in favour of DDA. DDA will also write a letter to DPCC and SDM to get the dumping of industrial waste stopped which is going on continuously into the water body.

**33) Low Depression at Dwarka, Sector-5, DDA Office Complex,**

**Lat/Long: 28° 35.600' N, 77° 03.500' E**

It is located in Sector-5, DDA office Complex in an about half an acre area. It is not a water body, only small depression exists as per the ATR submitted by DDA. However, the rainwater of the complex has been connected to the low lying area in the park. Deputy Director (Land Management) West Zone, DDA has been requested to provide Khasra No. Tree plantation is to be done around the area of depression in the rainy season.

**34) Kakrola, Kh. No. 184 (15-6) – DDA**

**G. No. 692**

As per the ATR submitted by DDA, there is a court case titled as Suraj Bhan & others V/s Union of India in the High Court of Delhi WP(C) 1472/2011. Latest court case status shall be intimated by Land Management Branch. More Plantation shall be done before monsoon season. Cleaning shall be completed by 30.06.17. DDA is to get TSM survey done through Revenue Deptt. in 15 days time.

**35) Kakrola, Kh. No. 194 (15-4) – DDA**

**G. No. 693**

As per the ATR submitted by DDA, cleaning and repair of boundary wall shall be completed up to 30.06.2017. It shall be connected to the nearby existing drain by DDA. More plantation shall be done before rainy season.

**36) Kakrola, Kh. No. 192 (8-17) – DDA**

**G. No. 692**

It is situated along MCD drain, but drain is having sewage and other waste water. MCD was directed to connect it to adjoining bigger drain and stop its flow into water body. DJB must help MCD in this activity. Water body



has been converted into dumping yard. Steps need to be taken to remove encroachment by DDA as revealed in TSM survey done earlier.

As per the ATR submitted by DDA, the case for removal of encroachment is being processed by EE/WD-15. The waste water has to be stopped by MCD and DJB. More plantation shall be done before rainy season.

**37) Kakrola, Kh. No. 175 (17-10) – DDA**

**G. No. 695**

It is an encroached area. Direction had been given to Revenue Deptt. to do TSM survey within 15 days from its own to clarify the status.

As per the ATR submitted by DDA, SDM Dwarka has been requested vide letter No F1(6)Misc/WD-6/DDA/551 dt 07.06.2017 for TSM Survey. More plantation shall be done before rainy season.

**38) Kakrola, Kh. No. 195/41(1-9) – DDA**

**G. No. 693**

It is converted into building area as Panchayat Bhawan. It is known as Suraj Kund. At present, it is not a water body. Earlier it was a water body. Directions were given to DDA to install Rain Water Harvesting System within one month and plantation during rainy season.

As per the ATR submitted by DDA, EE/WD-6 has been directed to explore possibility of rain water harvesting. Building for panchayat bhawan is already existing at the site so it should be deleted from the list.

**39) Kakrola, Kh. No. 14/20/2(1-8) – DDA**

**G. No. 694**

It is located opposite to NSIT and Opposite Rajesh Auto Mobiles adjacent to main road. It is a vacant land. Dumping is going on. DDA was asked to clean the site from dumping and do tree plantation around it during coming Monsoon season.

**40) Luharheri, Kh. No. 4/26 (3-11) – DDA**

**G. No. 732**

DDA officials informed that this water body has been transferred to Delhi Archaeological Department. A baoli exists at site. This area is under green belt and is located between Gangotri Apartment and Dwarka International School, Sector - 12. Direction has been given to Revenue Deptt. to conduct TSM survey from its own in 15 days time. Plantation is to be done during monsoon season by DDA.

As per the ATR submitted by DDA, Deputy Director (Horticulture) have been directed to inspect the site and explore the possibility of plantation in the area. It has already been transferred from DDA to ASI.

**41) Toganpur, Kh. No. 1/183(12-2) – DDA**

**G. No. 839**

It is a natural water body and is located in forest area of DDA. It is located at Bharat Vandana Udhaan, Sector-20, Dwarka. Directions were given to Delhi Jal Board to make a short term water rejuvenation plan and implement for which DDA agreed to. Directions were given to DDA to make it as as Biodiversity zone.

As per the ATR submitted by DDA, the area is properly protected and maintenance plan of the area is under consideration by Landscape branch of DDA for whole of Bharat Vandna Park. This water body is a part of that area. Further it should be developed as Biodiversity park similar to Aravalli biodiversity park under the guidance of Prof. C.R. Babu without delay.

**42) Shahbad Mohd. Pur, Kh. No. 1/72 (28-13) – DDA (Distt. New Delhi)**

**G. No. 983**

It is located next to railway station crossing. Gate has been restored. Tree plantation is to be done during Monsoon. Boundary wall needs to be repaired in 15 days time.

**43) Shahbad Mohd. Pur, Kh. No. 1/535 (31-6) - DDA - (Distt. New Delhi)**

**G. No. 984**

It exist near to Govt. School. At site, park exists. Direction were given to make recharging pits at corners and plantation around the water body area during coming monsoon.

As per the ATR submitted by DDA, more plantation shall be done before rainy season. Recharging pits are not feasible as the drain water coming from village is quite dirty and consist of sewerage as well. However shallow recharging pits needs to be there on corners with gentle slope towards then for draining water from rain and irrigation.

Apart from above directions, following needs to be carried out:-

1. Proper map and brief document of each water body be made with planned landscape having area, boundary and right of concession be prepared and submitted to this office with 15 days.
2. Plantation should be done by Horticulture Department of DDA during this Monsoon.
3. Debris dumped be removed by June' 2017 from all water bodies.
4. Officers both from Engineering and Horticulture Department of DDA not below from Executive Engineer, Deputy Director (Hort.) and SO (Hort.) should be present in the next inspection.
5. Next inspection of all the water bodies will be conducted on **15.6.2017 and 16.6.2017 from 9:00 am onwards.**



**(Dr. S.D. Singh)**  
CEO-DPGS,

Nodal officer, Water Bodies